GE CT System PM Checklist Q1

Site: Green Light	Date: 8 4 22 Service Report#:		
System ID#: CT3			
Service Engineer: Alejandro famires	<u> </u>		
	Inspected	Cleaned	Passed
Procedure		- 	
COMPUTER		· · · · · · · · · · · · · · · · · · ·	
Check fans/Clean/Vacuum all exhaust vent holes	\checkmark		
CONSOLE			
Check fans/Clean/Vacuum console interior		$\overline{}$	
Verify emergency off buttons (table/console)			
Inspect Keyboard, mouse, and monitors cable connections and			
operation		\checkmark	
GANGRY	·		-
Verify tilt operation			
Inspect/ Clean Mylar window	$\sqrt{}$	$\overline{}$	
Inspect/ Clean All fans and filters			
Handling & Removal of Slip Ring Brush Debris			
Slip Ring Vacuuming		V	
Verify Gantry balance			
SYSTEM			,
Check operation of final scan abort push-buttons			
Inspect Error Logs for bad channels, tube spits, and HV issues			1
Record current tube mAs or exams			
Verify Recon Data Path passes			
Verify Das Tools auto test passes	V		
Verify Collimator functional test			
Verify Collimator Aperture			
Inspect/Clean/Check operation of table cradle drive			
General Cleaning of all covers		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
Inspect high voltage connections			

GE CT System PM Checklist Q1

	nspected	Passed
Procedure		
SYSTEM (Continued)		
Inspect tube cooling connections	\	
Verify table movement		V
Verify laser light alignments		V
Verify console date and time		V.
Verify console network, archive and filming queues are empty		
Perform Quality Assurance Scans	V	
Create system state backup	V	

Notes:				
	System is	fully function	nal à passe	d QA scaus.
	0	U		
		•		
é	· · · · · · · · · · · · · · · · · · ·		Date:	4/22
Service Eng	gineer Signature:		Dale	