

GREEN LIGHT IMAGING

LEAD APRON / THYROID COLLARS ANNUAL EVALUATION

CT UNIT # 1

ITEM	TESTED BY	DATE CHECKED	SATISFACTORY VISUAL/FLUORO	DEFECTIVE DISCARD
Apron 1	Virgil Quinn	5/01/2020	Good Condition	
Thyroid 1	Virgil Quinn	5/01/2020	Good Condition	

CT UNIT # 2

ITEM	TESTED BY	DATE CHECKED	SATISFACTORY VISUAL/FLUORO	DEFECTIVE DISCARD
Apron 2	Virgil Quinn	5/01/2020	Good Condition	
Thyroid 2	Virgil Quinn	5/01/2020	Good Condition	

CT UNIT # 3


ITEM	TESTED BY	DATE CHECKED	SATISFACTORY VISUAL/FLUORO	DEFECTIVE DISCARD
Apron 3	Virgil Quinn	5/01/2020	Good Condition	
Thyroid 3	Virgil Quinn	5/01/2020	Good Condition	

CT UNIT # 4

ITEM	TESTED BY	DATE CHECKED	SATISFACTORY VISUAL/FLUORO	DEFECTIVE DISCARD
Apron 4	Virgil Quinn	5/01/2020	Good Condition	
Thyroid 4	Virgil Quinn	5/01/2020	Good Condition	

Comments:

No breaks on lead lining of protective garments were detected.
Thyroid shields also intact.




George Toti, CRT

GLI CT Lead Technologist / Supervisor

05.21.20

Date



Robert Benson, M.D.
GLI Medical Director

6/1/20

Date