

GREEN LIGHT IMAGING

LEAD APRON / THYROID COLLARS ANNUAL EVALUATION

CT UNIT # 1

ITEM	TESTED BY	DATE CHECKED	SATISFACTORY VISUAL/FLUORO	DEFECTIVE DISCARD
Apron 1	Virgil Quinn	2/24/2023	Good Condition	
Thyroid 1	Virgil Quinn	2/24/2023	Good Condition	

CT UNIT # 3


ITEM	TESTED BY	DATE CHECKED	SATISFACTORY VISUAL/FLUORO	DEFECTIVE DISCARD
Apron 3	Virgil Quinn	2/24/2023	Good Condition	
Thyroid 3	Virgil Quinn	2/24/2023	Good Condition	

CT UNIT # 4

ITEM	TESTED BY	DATE CHECKED	SATISFACTORY VISUAL/FLUORO	DEFECTIVE DISCARD
Apron 4	Virgil Quinn	2/24/2023	Good Condition	
Thyroid 4	Virgil Quinn	2/24/2023	Good Condition	

Comments:

No breaks on lead lining of protective garments were detected.
Thyroid shields also intact.



Virgil Hill Quinn, CRT
GLI CT Technologist

2/24/23

Date