

# GREEN LIGHT IMAGING

## LEAD APRON / THYROID COLLARS ANNUAL EVALUATION

### CT UNIT # 1

ITEM	TESTED BY	DATE CHECKED	SATISFACTORY VISUAL/FLUORO	DEFECTIVE DISCARD
Apron 1	Nicholas Alvarez	5/3/2024	Good Condition	
Thyroid 1	Nicholas Alvarez	5/3/2024	Good Condition	

### CT UNIT # 3


ITEM	TESTED BY	DATE CHECKED	SATISFACTORY VISUAL/FLUORO	DEFECTIVE DISCARD
Apron 3	Nicholas Alvarez	5/3/2024	Good Condition	
Thyroid 3	Nicholas Alvarez	5/3/2024	Good Condition	

### CT UNIT # 4

ITEM	TESTED BY	DATE CHECKED	SATISFACTORY VISUAL/FLUORO	DEFECTIVE DISCARD
Apron 4	Nicholas Alvarez	5/3/2024	Good Condition	
Thyroid 4	Nicholas Alvarez	5/3/2024	Good Condition	

### Comments:

No breaks on lead lining of protective garments were detected.  
Thyroid shields also intact.

  
\_\_\_\_\_  
Nicholas Alvarez, CRT  
GLI CT Technologist

5-3-24  
\_\_\_\_\_  
Date