

Medwrks LLC
701 S Gifford, Unit 108
SanBernadino, CA 92408 Usa
michael.stephens@medwrks.com
http://Medwrks.com



INVOICE

BILL TO

Green Light Imaging, LLC
8348 Rosemead Blvd
Pico Rivera, CA 90660
United States

INVOICE # Service Report

DATE 11/02/2020

DUE DATE 11/17/2020

TERMS Net 15

DESCRIPTION	QTY	RATE	AMOUNT
Service:MRI PM GE MRI PM SERVICE NON CONTRACTED	1	0.00	0.00
Service:Service Rate On Site 11:30 pm PM Checked and removed metal from magnet. Ran ISO calibrations, x, y, z grad cals, and Head and Body SNR and Gain. Did DC offsets and cleaned up software. him and body snr due to no LV shim phantom and body phantom on site.. Off Site 3:30 am travel:Standard Travel (deleted) Standard hourly Travel Rate			

PAID

Completed MRI p.m. as scheduled by manufacture all test and calibration is required were completed system is functioning within manufacture specifications

BALANCE DUE

\$0.00